

## PRODUCT OBSOLESCENCE NOTICE

September 30, 2009

Dear Customer,

Murata Power Solutions (MPS) hereby gives official notification that the following product(s) you may have purchased from us are becoming obsolete with immediate effect:

Product Part Number	Our internal Reference
BCP-3.3/15-2.5/15-D24	8101013
BCP-3.3/15-2.5/15-D48	8101009
BCP-3.3/15-2.5/15-D48N	8101011
BCP-30530	8125275
BCP-30533	8101001
BCP-30593	8101006
BCP-30600	8112654
BCP-30636	8101007
BCP-30755	8100835
BCP-31043	8100900
BCP-31102	8100901
BCP-31102-Y	8700901
BCP-5/15-3.3/15-D24	8101004
BCP-5/15-3.3/15-D24N	8101003
BCP-5/15-3.3/15-D48	8101000
BCP-5/15-3.3/15-D48-30752	8101010
BCP-5/15-3.3/15-D48-30976	8101023
BCP-5/15-3.3/15-D48L1	8125282
BCP-5/15-3.3/15-D48L2	8125283
BCP-5/15-3.3/15-D48L3	8125284
BCP-5/15-3.3/15-D48N	8112653
BCP-5/15-3.3/15-D48NL1	8125278

Via this notice we are offering our customers the opportunity for a last time or lifetime buy (LTB) and **we will accept orders until December 31, 2009**. Please note that this LTB may be subject to a minimum order quantity.

Multiple releases will be accepted with a constraint that **no releases may be scheduled past a ship date of March 31, 2010**.

Once placed, LTB orders cannot be cancelled, rescheduled or returned for non-quality reasons. Quality issues need to be identified and communicated within 30 days of shipment.

**Please note that there may be direct or alternate replacements for most of these products.**

Should you have any questions or concerns please contact your local MPS Representative, Distributor or Regional Sales Manager. <http://www.murata-ps.com/offices.html>